

WS-10 Scale Indicator



Resolution	Display: 30,000
Weighing Units	Lb/kg Selectable
Functions	Check Weighing, Counting, Totalizing
Construction	Stainless
Display	7-segment LCD w/Back Light
Load Cell Excitation	5 VDC, 4 Wire connection, 6 Cells of 350
Load Cell Connection	Terminal Strip
Keyboard	8 Multi-Foil
Interface	RS232
Mounting	Table or Wall, Bracket included
Operation Temperature	14 F to 104 F
Dimensions	8" x 5.5" x 3.25"
Power	110VAC or Rechargeable Battery
Gross Weight	6.4 lbs
NTEP	10-031